



# Brilliant Remover

## Cleaner for UV Fluorescent Tracers

**BRILLIANT REMOVER** (UV Fluorescent tracers cleaner) removes UV tracers from tools, surfaces, charge valves and any contaminated parts that have been involved during the operation of leak searching. It is crucial to prevent future fluorescent traces that can lead to false positives during other search operations.

Instructions: Spray **BRILLIANT REMOVER** on the dirt parties and remove with a cloth or paper. It removes grease and pigments without damaging the surfaces.

**BRILLIANT REMOVER** should be used by an experienced operator, provided the specific personal protective equipment.

